Oras Care


Installation and maintenance guide





4-7


8-11


12



13-17



18


19-20

5711F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.18 l/s (300 kPa)
95 kPa (0.1 l/s)
max. +80°C







mpi.oras.com/5711F

5701F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.13 l/s (300 kPa)
180 kPa (0.1 l/s)
max. +80°C







mpi.oras.com/5701F

5791F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.18 l/s (300 kPa)
95 kPa (0.1 l/s)
max. +80°C







mpi.oras.com/5791F

5715F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.18 l/s (300 kPa)
95 kPa (0.1 l/s)
max. +80°C







mpi.oras.com/5715F

5713F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.18 l/s (300 kPa)
95 kPa (0.1 l/s)
max. +80°C







mpi.oras.com/5713F

5730F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.21 l/s (300 kPa)
275 kPa (0.2 l/s)
max. +80°C







mpi.oras.com/5730F

5735F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.21 l/s (300 kPa)
275 kPa (0.2 l/s)
max. +80°C






mpi.oras.com/5735F

5738F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.21 l/s (300 kPa)
275 kPa (0.2 l/s)
max. +80°C







mpi.oras.com/5738F


5739F

I (ISO 3822)
EN 817
50 - 1000 kPa
0.2 l/s (300 kPa)
300 kPa (0.2 l/s)
max. +80°C






mpi.oras.com/5739F












④




max.
1600 kPa











1








1


2














1




2 A



B




C







①





ON
OFF



OFF
ON




②



⑤








②




⑤⑥











②





⑤





⑧
















159670/10




159667/10






②




④




⑤


1




2





3



22








CLEANING.ORAS.COM


5711F , 5701F, 5791F

1	1004914V	L=162
1	1005294V	L=136
2	1000664V	
3	158726	
4	158890	
5	1000780V	
6	602610V	
7	602283V	Laminar
7	232211	
8	1002371V	




5730F , 5735F , 5713F , 5715F

1	1004914V	L=162
1	1005294V	L=136
2	602589V	
3	158726	
4	158890	
5	602520V	L=132
5	1005585V	L=210
6	1002207/10	40° - 80°
6	1001406/10	120°
7	1000780V	
8	602610V	
9	232210	B
9	232211	A
10	601097/10	
11	158735	
12	159423/10	
13	602600V	
14	1005697V	
15	1002371V	
16	158825	



5739F , 5738F

1	232201	
2	159695V	
3	159670/10	120°
3	159667/10	60°/0°
3	159667V	60°/0°
4	159499	
5	1005294V	L=136
5	1004914V	L=162
6	602589V	
7	158726	
8	158890	
9	602600V	
10	1005697V	
11	1002371V	
12	158825	
13	1000780V	
14	602610V	



Oras Group is a powerful European provider of sanitary fittings: the market leader in the Nordics and a leading company in Continental Europe. The company's mission is to make the use of water easy and sustainable and its vision is to become the European leader of advanced sanitary fittings. Oras Group has two strong brands: Oras and Hansa.

The Group's head office is located in Rauma, Finland, and the Group has three manufacturing sites: Kralovice (Czech Republic), Olesno (Poland) and Rauma (Finland). Oras Group employs approximately 1,200 people in twenty countries. Oras Group is owned by Oras Invest, a family company and an industrial owner.

943348-04-20

ORAS Ltd
Isometsäntie 2, P.O. Box 40
FI-26101 Rauma
Tel. +358 2 83 161
Fax +358 2 831 6300
info.finland@oras.com
www.oras.com